

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problems Mailbox.**

FIG. 1 of 05493260




FIG 1




Fig. 2.

FIG. 2a




Fig. 2a







FIG 3

FIG 3 of 00000000





FI 66







FIG 7

519-88

Fig. 9 is a cross-sectional diagram of a device with two vertical tubes (41b) and a common base (41). The base contains a wavy, textured material. The tubes are connected to a common base (41) and have a wavy, textured material (41a) inside them. The tubes are labeled 41b and 32. The base is labeled 41. The wavy material inside the tubes is labeled 41a. The tubes are connected to a common base (41) and have a wavy, textured material (41a) inside them. The tubes are labeled 41b and 32. The base is labeled 41. The wavy material inside the tubes is labeled 41a.

FIG. 10







Fig 12



Form 0629260